

COLD & DRY WINTERS = INCREASED HUMIDIFIER DEMAND

Remember to check your cylinders regularly!



Thank you for purchasing a NORTEC humidifier. Over thirty years ago, we saw the need for a humidifier design that would end the time-consuming and costly maintenance that was required by other humidifiers. The main problem to overcome was to easily remove the minerals that are left behind when water is boiled. At the same time, a humidifier was needed to produce clean steam and maintain long-term efficient operation.

The NORTEC electrode steam humidifier, with disposable cylinder, meets all of the above criteria.

As clean steam is produced, the minerals that are in the water remain in the steam generating cylinder and are periodically removed through the automatic drain system. NORTEC's patented auto-adaptive control system is designed to produce 100% of rated output capacity right up until end of cylinder life. At this time, the cylinder is easily removed and replaced with a new clean cylinder.

While other humidifiers must be totally disassembled for cleaning and require hazardous acids to remove the minerals, the cylinder in your NORTEC humidifier is easily removed and replaced. Since the cylinders are produced of inert plastics and retain only the water borne minerals, disposal problems are at a minimum.

This ease of cleaning and cylinder replacement is one of the main features that helps reduce customer maintenance costs. It allows optimum service from the humidifier and keeps the time required for maintenance to a minimum.



- ▶ Low cost
- ▶ Clean
- ▶ Easy maintenance

AUTHORIZED AGENT

The logo for Walter Meier, with "walter" in a blue, lowercase, sans-serif font and "MEIER" in a larger, blue, uppercase, sans-serif font below it.

Replacement Cylinder Order Form



Name		
Company		
Address		
City	State/Province	Zip/Postal Code
Phone	Fax	

Cylinder #	Part #	Humidifier Specifications	Price each	Quantity	Total
104	1519704	005/010 lbs/hr 380 - 600 V 1 ph	\$159.00		
201	1519001	005/010 lbs/hr 110-240v 1ph	\$159.00		
202	1519002	005/010 lbs/hr 110-277v 1 ph	\$159.00		
203	1519003	005/010 lbs/hr 347-380V 1 ph	\$159.00		
204	1519004	005/010 lbs/hr 440-600v 1 ph	\$159.00		
301/321	1519020	020 lbs/hr 208-277v 1 ph	\$186.00		
303	1519023	020 lbs/hr 208 - 240 V 3ph	\$186.00		
305	1519025	020 lbs/hr 347 - 380 v 1ph	\$186.00		
309	1519029	020 lbs/hr 440 - 600 V 1 ph	\$186.00		
311	1519031	020 lbs/hr 440 - 600 V 3ph	\$186.00		
403/421	1519040	030 lbs/hr 208 - 240V 3ph	\$229.00		
411	1519051	030 lbs/hr 440 - 600 V 3ph	\$229.00		
601/621	1519080	50/75/100/150/200 lbs/hr 208 - 240V 3ph	\$284.00		
607	1519087	050/075/150 lbs/hr 460/575V 100/200 lbs/hr, 575V	\$284.00		

The above are suggested prices for NORTEC standard replacement cylinders. Prices may vary according to geographic location and are subject to change without notice. Freight is not included.

Replacement cylinders can be ordered directly from your local agent. You can also fill in this form and forward it directly to Walter Meier (NORTEC). We will have our agent contact you.

With each replacement cylinder, a new drain o-ring is supplied. Please find it attached to this form.

Thank you for choosing NORTEC humidifiers.

U.S.A.

Walter Meier (Climate USA) Inc.
826 Proctor Avenue
Ogdensburg, NY 13669

CANADA

Walter Meier (Climate Canada) Ltd.
2740 Fenton Road
Ottawa, Ontario K1T 3T7

TEL: 1.866.NORTEC1
FAX: 613.822.7964
EMAIL: sales@humidity.com
WEBSITE: www.humidity.com

Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>